

SPACE COAST EMERGENCY TARPING

STORM EVENT & AERIAL ROOF DOCUMENTATION REPORT

Observational documentation, prepared for the property owner.

PROPERTY

Reina Jaquez

1202 Bedrock Ave NE, Palm Bay, FL, 32907

REPORT DATE

Jul 19, 2026

PREPARED BY

Space Coast Emergency Tarping

STORM DATE

Sep 10, 2024

STORM TYPE

Hail

MAX WIND / HAIL

75 mph · 1.25" hail

DISTANCE

4.7 mi

0 aerial photos reviewed · 0 observations flagged · Heat map: available

A no-cost courtesy report - no service is being sold.

Storm Impact Heat Map


Property location and documented storm activity in the surrounding area.

Heat map data was not available at the time this report was generated.

Qualifying Storm Events Near Property

Source: NOAA/NWS Storm Reports - Window: last 36 months - Within 15 mi of property

DATE	TYPE	WIND	HAIL	DISTANCE	SOURCE
Mar 15, 2025	Hail	75 mph	1.25"	4.7 mi	NOAA/NWS
Sep 10, 2024	Hail	75 mph	1.25"	4.7 mi	NOAA/NWS
May 24, 2025	Hail	68 mph	1"	4.7 mi	NOAA/NWS
Nov 15, 2024	Hail	62 mph	0.88"	5.1 mi	NOAA/NWS



● Property

Property Profile

Property data sourced from connected county property appraiser records.

OWNER OF RECORD	Reina Jaquez
SITE ADDRESS	1202 Bedrock Ave NE, Palm Bay, FL, 32907

Most Recent Roof Permit

Permit data was not available at the time this report was generated.
Unavailable data should not be interpreted as confirmation that no permit exists.

Aerial Overview & Key Observations

Drone imagery captured from the property driveway. No personnel walked the roof surface.

No aerial imagery attached.

OBSERVATION TAGS

Overview documentation - no notable indicators flagged in this image set.

Field Summary

This report serves as a useful baseline for future weather events. No notable observations were found during the inspection, suggesting that the property is in good condition. It's always a good idea to keep an eye on potential weather impacts as part of regular property maintenance.

Recommended Next Steps

- 1 Schedule a no-cost roof condition review.
- 2 Document interior ceiling stains, water marks, or active leaks.
- 3 Review exterior conditions with a qualified professional.
- 4 Homeowner decides whether to contact their insurance carrier.
- 5 Watch for changes after the next rain.

CONTACT

Space Coast Emergency Tarping

Call/Text: 1 (877) 321-8277

Email: info@scetarping.com

Methodology & Disclosure

Image Capture

Imagery was captured by aerial drone operated from the property driveway. No personnel walked on the roof surface during this documentation.

Storm Data Sources

Storm event records sourced from NOAA Storm Prediction Center, National Weather Service local storm reports, and MRMS radar archives. Distance is calculated as great-circle distance from event coordinates to property coordinates.

Heat Map Data Sources

Heat map imagery provided by satellite tile providers (Google Static Maps / Mapbox), with photo capture markers overlaid based on EXIF coordinates and concern level.

Property Data Sources

Property characteristics sourced from connected county property appraiser public records.

Permit Data Sources

Permit data sourced from connected jurisdiction permit portals where coverage is available.

AI-Assisted Captioning

Photo captions and the field summary were generated with AI assistance based solely on the captured drone imagery and structured storm data. Captions describe visible features observationally; they do not constitute a damage assessment.

Important Disclosure

This report is observational documentation only. It is not a structural inspection, not an engineering report, not an insurance claim, and does not guarantee any insurance outcome. No diagnosis of damage is asserted. A licensed professional should evaluate any concerns identified in this document.

Data Availability Note

Some property, permit, or map data may be unavailable depending on connected public records, jurisdiction access, or data provider coverage. Unavailable data should not be interpreted as confirmation that no record exists.